



DARE MRO DATA after receiver swap

HAMDI MANI

06/29/2012

File: 2012_172_00.dat
Date/ Time: 2012-06-21 08:00



Header Data



Last valid data

2.0120e+003
172.0000e+000
6.0000e+000
20.0000e+000
2.0000e+000
57.0000e+000
53.5961e+000
2.0000e+000
0.0000e+000
30.0000e+000
330.1392e+000


3620th data block
(spectrum)

06/20/2012 @2:57

Receiver disconnected

2.0120e+003
172.0000e+000
6.0000e+000
20.0000e+000
3.0000e+000
0.0000e+000
33.6033e+000
2.0000e+000
1.0000e+000
30.0000e+000
6.5527e+000


06/20/2012 @3:00:33



2.0120e+003
 172.0000e+000
 6.0000e+000
 20.0000e+000
 3.0000e+000
 0.0000e+000
 36.5525e+000
 2.0000e+000
 0.0000e+000
 30.0000e+000
 325.2544e+000

Receiver connected


06/20/2012 @3:00:36



2.0120e+003
 172.0000e+000
 6.0000e+000
 20.0000e+000
 3.0000e+000
 0.0000e+000
 39.5016e+000
 2.0000e+000
 1.0000e+000
 30.0000e+000
 325.2544e+000

Receiver on load


06/20/2012 @3:00:39



2.0120e+003
 172.0000e+000
 6.0000e+000
 20.0000e+000
 3.0000e+000
 0.0000e+000
 42.4507e+000
 2.0000e+000
 0.0000e+000
 30.0000e+000
 325.3735e+000

06/20/2012 @3:00:42

Receiver on antenna



2.0120e+003
 172.0000e+000
 6.0000e+000
 20.0000e+000
 3.0000e+000
 0.0000e+000
 45.3998e+000
 2.0000e+000
 1.0000e+000
 30.0000e+000
 325.3735e+000

06/20/2012 @3:00:45

Receiver on load